

**XRF Survey Results - Gateway South Redevelopment Properties**

Sample Number	Substrate	Component	Color	Location / Description	XRF Reading (mg/cm2)	LBP (Pos. or Neg.)
1645-01	Wood	Calibration	Red	(Calibration)	0.8	Positive
1645-02	Wood	Calibration	Red	(Calibration)	0.9	Positive
1645-03	Wood	Calibration	Red	(Calibration)	0.8	Positive
1645-04	Wood	Door frame	White	1645 Warner St. Warehouse No 2, Side C	9.2	Positive
1645-05	Wood	Door frame	White	1645 Warner St. Warehouse No 2, Side C	3.7	Positive
1645-06	Wood	Wall	White	1645 Warner St. Warehouse No 2, Side C, wall made of door panels	0.6	Negative
1645-07	Wood	Wall	White	1645 Warner St. Warehouse No 2, Side C, wall made of door panels	5.7	Positive
1645-08	Wood	Wall	Brown	1645 Warner St. Warehouse No 2, Side C, wall made of door panels	9.6	Positive
1645-09	Wood	Wall	White	1645 Warner St. Warehouse No 2, Side D	1.1	Positive
1645-10	Wood	Door frame	White	1645 Warner St. Warehouse No 2, Side A	0.2	Negative
1645-11	Wood	Door frame	Green	1645 Warner St. Warehouse No 2, Side B	0.5	Negative
1645-12	Wood	Door panel	Green	1645 Warner St. Warehouse No 2, Side B	0.4	Negative
1645-13	Block	Wall	Green	1645 Warner St. Warehouse No 2, Side A	1.2	Positive
1645-14	Wood	Door frame	Green	1645 Warner St. Warehouse No 2, Side A	0.6	Negative
1645-15	Wood	Door	Grey	1645 Warner St. Warehouse No 2, Side A	1.6	Positive
1645-16	Block	Wall	Green	1645 Warner St. Warehouse No 2, Side A	0.9	Positive
1645-17	Metal	Door frame	Brown	1645 Warner St. Warehouse No 2, Side B	-0.4	Negative
1645-18	Metal	Support beam	Brown	1645 Warner St. Warehouse No 2, On roof	-0.1	Negative
1645-19	Block	Wall	Black	1645 Warner St. Warehouse No 2, Inside door room, side A	0.6	Negative
1645-20	Metal	Shelf rail	Green	1645 Warner St. Warehouse No 2, Inside door room, side A	-0.2	Negative
1645-21	Block	Wall	White	1645 Warner St. Warehouse No 2, Inside door room, side A	0.3	Negative
1645-22	Metal	Support beam	White	1645 Warner St. Warehouse No 2, Tub/sink area, Beam at entrance, side B	6.8	Positive
1645-23	Block	Wall	White	1645 Warner St. Warehouse No 2, Tub/sink area, side C	0.5	Negative
1645-24	Block	Wall	Light Grey	1645 Warner St. Warehouse No 2, Radiator cover room, side B	0.5	Negative
1645-25	Wood	Door panel	White	1645 Warner St. Warehouse No 2, Door between radiator cover room and tub/sink area	2.1	Positive
1645-26	Wood	Door panel	White	1645 Warner St. Warehouse No 2, Door to room on right, entrance of tub/sink area	-0.6	Negative
1645-27	Metal	Support beam	White	1645 Warner St. Warehouse No 2, Tub/sink room	2.5	Positive
1645-28	Metal	Shelf rail	Blue	1645 Warner St. Warehouse No 2, Shelf for windows in tub/sink room	0.1	Negative
1645-29	Metal	Shelf rail	Green	1645 Warner St. Warehouse No 2, Shelf for windows in tub/sink room	0.2	Negative
1645-30	Metal	Shelf rail	Orange	1645 Warner St. Warehouse No 2, Shelf for windows in tub/sink room	0.2	Negative
1645-31	Metal	Door frame	White	1645 Warner St. Warehouse No 2, Shutter frame, side A	0.3	Negative
1645-32	Metal	Door	Red	1645 Warner St. Warehouse No 2, Shutter frame, side A	0.5	Negative
1645-33	Block	Wall	Red	1645 Warner St. Warehouse No 2, Next to Shutter, side A	0.6	Negative

**XRF Survey Results - Gateway South Redevelopment Properties**

Sample Number	Substrate	Component	Color	Location / Description	XRF Reading (mg/cm2)	LBP (Pos. or Neg.)
1645-34	Block	Wall	White	1645 Warner St. Warehouse No 2, Wood planks area, side A	0.7	Positive
1645-35	Wood	Pillar	White	1645 Warner St. Warehouse No 2, Wood planks area	0.2	Negative
1645-36	Block	Wall	Red	1645 Warner St. Warehouse No 2, Between mirror/sink and door panel room	0.6	Negative
1645-37	Wood	Door frame	White	1645 Warner St. Warehouse No 2, Entrance door to door panel room	0.7	Positive
1645-38	Wood	Door panel	White	1645 Warner St. Warehouse No 2, Entrance door to radiator room	1.1	Positive
1645-39	Metal	Door panel	Grey	1645 Warner St. Warehouse No 2, Exit door in radiator room	-0.1	Negative
1645-40	Metal	Door frame	Red	1645 Warner St. Warehouse No 2, Exit door in radiator room	0.5	Negative
1645-41	Metal	Support beam	Yellow	1645 Warner St. Warehouse No 2, Behind entrance door into radiator room	0.4	Negative
1645-42	Block	Wall	Grey	1645 Warner St. Warehouse No 2, Wood planks area in radiator room	1.1	Positive
1645-43	Wood	Door	Green	1645 Warner St. Warehouse No 1, Entrance room side D	0.4	Negative
1645-44	Wood	Door frame	Green	1645 Warner St. Warehouse No 1, Entrance room side D	0.6	Negative
1645-45	Wood	Window frame	Green	1645 Warner St. Warehouse No 1, Entrance room side D	0.6	Negative
1645-46	Wood	Wall	Dark green	1645 Warner St. Warehouse No 1, Above entrance door, side D	2.3	Positive
1645-47	Wood	Door	White	1645 Warner St. Warehouse No 1, Small display bathroom	0.2	Negative
1645-48	Wood	Wall	White	1645 Warner St. Warehouse No 1, Wall outside display bathroom	0.4	Negative
1645-49	Block	Wall	White	1645 Warner St. Warehouse No 1, Wall on side B	0.9	Positive
1645-50	Metal	Door frame	Light Green	1645 Warner St. Warehouse No 1, Entrance to store room 1	0.3	Negative
1645-51	Metal	Stair railing	Green	1645 Warner St. Warehouse No 1, Stair Rails in store room 1	0.0	Negative
1645-52	Metal	Stair	White	1645 Warner St. Warehouse No 1, Stair landing	9.9	Positive
1645-53	Metal	Support beam	Green	1645 Warner St. Warehouse No 1, Next to stairs	0.5	Negative
1645-54	Wood	Wall	White	1645 Warner St. Warehouse No 1, Loft in store room 1	0.4	Negative
1645-55	Block	Wall	White	1645 Warner St. Warehouse No 1, Interior shutter room in store room 1	0.8	Positive
1645-56	Block	Wall	Green	1645 Warner St. Warehouse No 1, Store room, side B	0.5	Negative
1645-57	Concrete	Floor	Yellow	1645 Warner St. Warehouse No 1, Estate room	1.0	Positive
1645-58	Wood	Door frame	Grey	1645 Warner St. Warehouse No 1, Estate room, side B	0.3	Negative
1645-59	Brick	Wall	White	1645 Warner St. Warehouse No 1, Estate room, side C	0.8	Positive
1645-60	Wood	Wall	Light Grey	1645 Warner St. Warehouse No 1, Estate room, side B	0.2	Negative
1645-61	Wood	Wall	Pink	1645 Warner St. Warehouse No 1, Wall made of door panels, side D	9.1	Positive
1645-62	Wood	Wall	Bluish Grey	1645 Warner St. Warehouse No 1, Wall made of door panels, side D	8.9	Positive
1645-63	Drywall	Wall	Light Blue	1645 Warner St. Warehouse No 1, Passage to Exit on side B of property	0.5	Negative

XRF Survey Results - Gateway South Redevelopment Properties						
Sample Number	Substrate	Component	Color	Location / Description	XRF Reading (mg/cm2)	LBP (Pos. or Neg.)
1645-64	Metal	Electric box	grey	1645 Warner St. Warehouse No 1, Electric box	0.3	Negative
1645-65	Wood	Door frame	White	1645 Warner St. Warehouse No 1, Exit door, side B	0.4	Negative
1645-66	Drywall	Wall	White	1645 Warner St. Warehouse No 1, Near womens lounge	0.4	Negative
1645-67	Wood	Door frame	White	1645 Warner St. Warehouse No 1, Womens lounge	-0.1	Negative
1645-68	Ceramic	Wall	Green	1645 Warner St. Warehouse No 1, Womens lounge	0.5	Negative
1645-69	Ceramic	Toilet tank	White	1645 Warner St. Warehouse No 1, Womens lounge	0.7	Positive
1645-70	Ceramic	Toilet bowl	White	1645 Warner St. Warehouse No 1, Womens lounge	0.6	Negative
1645-71	Ceramic	Sink	Off-white	1645 Warner St. Warehouse No 1, Womens lounge	0.8	Positive
1645-72	Wood	Door frame	Dark brown	1645 Warner St. Warehouse No 1, Womens lounge	0.6	Negative
1645-73	Wood	Door	Light peach	1645 Warner St. Warehouse No 1, Room 1120, Entrance door	0.6	Negative
1645-74	Wood	Door frame	Light peach	1645 Warner St. Warehouse No 1, Room 1120, lunch room	-0.1	Negative
1645-75	Wood	Door	White	1645 Warner St. Warehouse No 1, Room 1120, closet	0.1	Negative
1645-76	Wood	Door	Light peach	1645 Warner St. Warehouse No 1, Room 1120, office 1	0.6	Negative
1645-77	Wood	Door	Light peach	1645 Warner St. Warehouse No 1, Room 1120, Office 2	0.1	Negative
1645-78	Block	Wall	White	1645 Warner St. Warehouse No 1, Exterior wall of warehouse 1	1.1	Positive
1551-78	Wood	Stair rail	Light blue	1551 Russell Street, MCC - upper level offices	0.4	Negative
1551-79	Drywall	Stair rail	Light peach	1551 Russell Street, MCC - upper level offices	0.6	Negative
1551-80	Metal	Door	Light peach	1551 Russell Street, MCC - upper level offices	0.6	Negative
1551-81	Wood	Door frame	Light blue	1551 Russell Street, Toilet	0.6	Negative
1551-82	Ceramic	Sink	White	1551 Russell Street, Toilet	0.5	Negative
1551-83	Ceramic	Toilet tank	White	1551 Russell Street, Sink	0.5	Negative
1551-84	Ceramic	Toilet bowl	White	1551 Russell Street, Toilet	0.7	Positive
1551-85	Wood	Window sill	White	1551 Russell Street, Toilet	1.1	Positive
1551-86	Wood	Door	White	1551 Russell Street, Side A	0.6	Negative
1551-87	Wood	Window frame	Light blue	1551 Russell Street, Door from foyer towards office, side A	1.1	Positive
1551-88	Drywall	Wall	Yellow	1551 Russell Street, Foyer, side A	1.6	Positive
1551-89	Wood	Door frame	Peach	1551 Russell Street, Toilet, lower level, side A	0.3	Negative
1551-90	Drywall	Wall	Light peach	1551 Russell Street, Lower level office, side C	1.1	Positive
1551-91	Metal	Fire door rail	Black	1551 Russell Street, Lower level office, side B	0.5	Negative
1551-92	Block	Wall	White	1551 Russell Street, Fire door rails, side C	0.3	Negative
1551-93	Block	Wall	White	1551 Russell Street, Warehouse, side A	1.0	Positive
1551-94	Metal	Door panel	White	1551 Russell Street, Warehouse, side B	1.1	Positive
1551-95	Wood	Fire extinguisher box	grey	1551 Russell Street, Fire door, side C	0.2	Negative
1551-96	Wood	Wall	Red	1551 Russell Street, Side B	1.8	Positive
1551-97	Metal	Door	Dark green	1551 Russell Street, Side A (Rear door)	0.8	Positive
1551-98	Metal	Electric box	Grey	1551 Russell Street, Fire door, side C	0.5	Negative
1551-99	Metal	Stand for tank	Green	1551 Russell Street, Electric box	0.4	Negative
1551-100	Wood	Fire extinguisher box	Red	1551 Russell Street, Stand for 2000 gal chemical tank - back of warehouse	1.7	Positive
				1551 Russell Street, Back of warehouse	0.3	Negative

**XRF Survey Results - Gateway South Redevelopment Properties**

Sample Number	Substrate	Component	Color	Location / Description	XRF Reading (mg/cm <sup>2</sup> )	LBP (Pos. or Neg.)
1551-101	Metal	Door	Green	1551 Russell Street, Locker room	0.4	Negative
1551-102	Block	Wall	White	1551 Russell Street, Locker room	0.8	Positive
1551-103	Wood	Door	Green	1551 Russell Street, Locker room	5.6	Positive
1551-104	Metal	Stair rail	Green	1551 Russell Street, Exterior Stair, near office area	0.5	Negative
1551-105	Wood	Calibration	Red	(Calibration)	0.8	Positive
1551-106	Wood	Calibration	Red	(Calibration)	1.0	Positive
1551-107	Wood	Calibration	Red	(Calibration)	0.9	Positive
1551-108	Wood	Calibration	Red	(Calibration)	0.9	Positive
1551-109	Wood	Calibration	Red	(Calibration)	1.1	Positive
1551-110	Wood	Calibration	Red	(Calibration)	0.8	Positive
1525-111	Metal	Support beam	Orange	1525 Russell Street, Shed for chemical storage, opp, Dona Lee's office	2.2	Positive
1525-112	Metal	Support beam	White	1525 Russell Street, HF tank, front of brick door entrance	-0.3	Negative
1525-113	Metal	Support beam	Brown	1525 Russell Street, HF tank, front of brick door entrance	-0.2	Negative
1525-114	Brick	Wall	Red	1525 Russell Street, Brick door entrance	1.1	Positive
1525-115	Metal	Shelf	Orange	1525 Russell Street, Brick door entrance room	-0.2	Negative
1525-116	Brick	Wall	Light grey	1525 Russell Street, Warehouse	1.1	Positive
1525-117	Brick	Wall	White	1525 Russell Street, Warehouse	0.3	Negative
1525-118	Metal	Support beam	White	1525 Russell Street, Warehouse	0.2	Negative
1525-119	Metal	Support beam	Yellow	1525 Russell Street, Warehouse	0.3	Negative
1525-120	Metal	Support beam	Red	1525 Russell Street, Lower beam in warehouse	0.0	Negative
1525-121	Brick	Wall	Blue	1525 Russell Street, Warehouse	0.1	Negative
1525-122	Metal	Support beam	White	1525 Russell Street, Warehouse	0.2	Negative
1525-123	Metal	Tank	Orange	1525 Russell Street, Chemical storage tank, rear room in warehouse	2.5	Positive
1525-124	Metal	Door	Dark green	1525 Russell Street, Rear room in warehouse	0.8	Positive
1501-125	Wood	Wall	Light grey	1501 Russell Street, Warehouse office near entrance	-0.3	Negative
1501-126	Metal	Door	Grey	1501 Russell Street, Entrance door	0.1	Negative
1501-127	Wood	Pillar	White	1501 Russell Street, Warehouse	1.8	Positive
1501-128	Wood	Pillar	Red	1501 Russell Street, Warehouse	0.8	Positive
1501-129	Block	Wall	Grey	1501 Russell Street, Warehouse	0.8	Positive
1501-130	Block	Wall	White	1501 Russell Street, Warehouse	0.5	Negative
1501-131	Metal	Support beam	Orange	1501 Russell Street, Warehouse	0.2	Negative
1501-132	Wood	Wall	Blue	1501 Russell Street, Warehouse	0.1	Negative
1501-133	Wood	Wall	White	1501 Russell Street, Warehouse	0.4	Negative
1501-134	Wood	Door	Green	1501 Russell Street, Warehouse, office A	0.3	Negative
1501-135	Wood	Wall	Light grey	1501 Russell Street, Warehouse, office C	0.3	Negative
1501-136	Wood	Wall	Grey	1501 Russell Street, Warehouse, chemical processing area	0.1	Negative

**XRF Survey Results - Gateway South Redevelopment Properties**

Sample Number	Substrate	Component	Color	Location / Description	XRF Reading (mg/cm2)	LBP (Pos. or Neg.)
1501-137	Wood	Wall	White	1501 Russell Street, Warehouse, chemical processing area	0.4	Negative
1501-138	Concrete	Pillar	Yellow	1501 Russell Street, Warehouse, chemical processing area	2.0	Positive
1501-139	Wood	Pillar	White	1501 Russell Street, Warehouse, chemical processing area	1.2	Positive
1501-140	Metal	Door	Dark grey	1501 Russell Street, Warehouse, chemical processing area (totes)	12.6	Positive
1501-141	Wood	Door frame	Light peach	1501 Russell Street, Warehouse, upper level, above staging area	0.5	Negative
1501-142	Block	Wall	White	1501 Russell Street, Warehouse, upper level, above staging area	0.7	Positive
1501-143	Wood	Door	Dark green	1501 Russell Street, Warehouse, upper level, above staging area	0.7	Positive
1501-144	Block	Wall	Brown	1501 Russell Street, Exterior of warehouse	0.8	Positive
1501-145	Wood	Calibration	Red	(Calibration)	1.0	Positive
1501-146	Wood	Calibration	Red	(Calibration)	0.9	Positive
1501-147	Wood	Calibration	Red	(Calibration)	0.9	Positive